# FD Operations & Maintenance



Anton Moroz

Malargue, Jan 30, 2024

### Operations (shift 4.01.24 – 18.01.24)




#### **Weather**

- Lightning storms led to shutters closing all throughout the shift. On some nights almost no data taken.
- T2 ratios often above 50-80 Hz in all FDs although no clouds. Many runs were stopped automatically or manually almost every night of the shift
- T3 ratios often spiked many of the recorded events are invalid (manually checked)

#### Power outages

- 5.01 LL and LM
- 6.01 all except LA
- 7.01 all except LA
- 17.01 LL



Total event counts (T3 rate higher than real): LL – 619, LM – 1079, LA – 1168, CO – 790, HE – 767

Counts from good shifts: around 2500 per FD

## Operations (shift 4.01.24 – 18.01.24)



### <u>LL:</u>

- HV/LV issues throughout all shift in different bays, mostly bay 1. Sometimes resetting circuit boards helped, on other nights some bays were not run. Boards were swapped between bays 1 and 6 no noticeable effect.
- 5.01 Calibration after the night: in LL bays 1-5 and HE bay 3 were not recording events
- 17.01 electronic background for calibration could not be recorded (no output) calibration not performed

#### <u>CO:</u>

• Air conditioning motor problem – no replacement can be obtained locally. Temperatures in bays consistently higher than normal due to hot weather. Maintenance team thinking about the solution