

HEAT Hydraulic System

- Already fixed
- Hydraulic liquid have been replaced on three bays
- Spare parts have been replaced on bay 3

HEAT Air conditioning on DAQ container

- Still out of service.
- Getting support from Liebert representatives @ Argentina (<https://www.vertivco.com/es-latam/>)

The original provider (Emerson) is not giving the support for Liebert anymore

- Doing some routine checks on equipment

HEAT Shutter on bay 3

- Still out of service.
- Shutter damaged, out of axis.
- Work in progress.