

## HEAT UV Filter Cleaning

- June 25, 2018
- 1 Cal A after, 1 Cal A before




HEAT Bay 2 Before Cleaning



HEAT Bay 2 After Cleaning


## HEAT Cal A Diffuser

- Not loose parts (at least by eye)



## Coihueco bays temperature

- On failure there is a way to see it ...



**Photos provided by:**

- **Primo Vitale**
- **Leandro Gomez**